

- FREE CHLORINE
- BROMINE
- TOTAL CHLORINE
- ALKALINITY
- pH
- TOTAL HARDNESS








Code 2977



Immerse strip for 2 seconds. Remove with pads face UD. SHAKE ONCE TO REMOVE EXCESS WATER. Read immediately: FCI>TCI>Alk>pH>TH



Alkalinity ppm 0 40 80 120 180 240

pН 6.2 6.8 7.2 7.8 8.4 9.0 Purple color indicates excessive sanitizer

TH Total Hardness 100 250 450 800+

LaMotte Company, Chestertown, MD 21620 USA www.lamotte.com/insta

- Keep wet fingers out of the bottle.
- Close cap tightly after removing strip.
- In pools, immerse strip to a depth of
- In spas, turn off jets and immerse strip to a depth of 6".
- For best results read in natural dayliaht.
- Store in a cool. dry place.



Drop holding box and dotted tolerance line